



POWERMAX 800

1. 020361	Swirl Ring	7. 120304	Long Tip
2. 120573	Electrode	8. 020930	Nozzle Retaining
3. 120574	Long Electrode	9. 120301	Cap Retaining
4. 020350	Tip 50A	10. 120601	Hand Shield
5. 120282	Tip 50A	11. 120602	Machine Shiene
6. 120305	Long Tip 50A Conical	- 120556	Torch Body