

## HK-4B

- Permanent magnet and electromagnetic steel are good for better setting of machine, and keeping machine in welding line.
- Permanent magnet can avoid damaging the machine when power is cut.
- Suitable for corner welding for container girder and suitable for bevel welding and in narrow room.
- Inductor can stop the machine when it is out of workpiece.

Model No.	Supply Voltage	L*W*H	Up down	Forward Backward	Work Angle	Processing  Angle	Speed	Method of driving	Weight
HK-4B	AC220/50	135*445*248	60mm	60mm	+_45°	10°	0-900	Rubber wheel drive	11.6